

## REFERENCE from Van Hove Nurseries, Zaffelare, Belgium




Aquasonic NT4.1 units were placed in the underground tanks and in the irrigation reservoir. Two days after installing the Aquasonic all algae had died and after a rainstorm, the algae sunk to the bottom of the reservoir.



Previously the filter screen box needed cleaning 3 times a day. Now it needs cleaning once a fortnight



As a result of the biofilms in the underground tanks disappearing, and the bacteria being killed, improvement in root growth of all nursery plants is obvious after 1 week.



Before installing the Aquasonic NT4.1, the floor was very slippery with algae



After a few weeks: there is no algae on the floor; the floor is no longer slippery, it does not need cleaning and it dries out much quicker

N.B. Before an Aquasonic NT4 unit was installed at this site, a Dutch unit had been operational for 6 months without any effect on the algae. The Aquasonic killed the algae in 2 days!